



How to Specify Vibrating Screen



MAHAVEERA INDUSTRIES

Wire Mesh, Double Crimped Wire Meshes, Vibrating Screens, Metal Perforated Sheets, Expanded Metal, Test Sieves, etc.



Screens For Quarry and Mining Industries



Screen Installation Tips

A. Proper tensioning


Improper tensioning will cause secondary vibration of the screen that often leads to breakage of the screen.

B. Tensioning method of the screen

Use of hooks for proper tensioning of the screen is recommended. Note that stretching the screen flat significantly affects its service life.

C. Proper arc of support bars

Support bars must be arranged in a proper arc shape. Otherwise, tensioning of the screen comes to be uneven, leading to breakage of the screen.



Properly tension the screen as shown above

D. Constant tensioning

During operation, as the screen may become loose due to stretching and loosening of the hooks, it is important to check the screen, and retighten the hooks.

MAHAVEERA INDUSTRIES

Works Address :
R-342, TTC Industrial Area, M.I.D.C.,
Thane Belapur Road, Rabale,
Navi Mumbai - 400 701.

Screens for
Quarry and
Mining Industries

Contact : Ashok Jain (Cell.: 98201 05067)
Tel. off. : 2769 1505 • Fax.: 2769 2179
E-mail : wiremeshindia@gmail.com
Web. : www.wiremesh.co.in

Works Address :
R-342, TTC Industrial Area, M.I.D.C.,
Thane Belapur Road, Rabale,
Navi Mumbai - 400 701.

Contact : Ashok Jain (Cell.: 98201 05067)
Tel. off. : 2769 1505 • Fax.: 2769 2179
E-mail : wiremeshindia@gmail.com
Web. : www.wiremesh.co.in